

Oroville Spillways Update



Mike Inamine
Program Manager, Oroville Recovery
September 18th, 2019

Main Spillway





Emergency Spillway





Main Spillway: First Use

- April 2nd 2019 first spill
- Ramped up to 25,000 cfs on April 7-8
- Extensive surveillance and instrumentation
- Excellent spillway performance: surveillance metrics within design criteria and operational thresholds





Independent Oversight

 September 13th, 2018 Letter from Independent Board of Consultants

"We believe the completed project will be robust, reliable and resilient, and will restore the Oroville Dam project to continued safe operation."

 May 20th, 2019 Letter from Independent Board of Consultants

"...the BOC affirms that the reconstructed Oroville Spillway has been completed in accordance with the design documents, and is judged to be safe for continued use."



Public Access

- DWR commitment to local community to provide early, safe access
- Active construction site
- New and extensive security measures
- Phased access



Next Steps

- Construction closeout
- Rehabilitation contract



